



Experimental Analysis of Influencing Factors on Flow Stability of Water Flow Facilities

T. Meng¹, C. Xing¹, B. Wu², C. Wang¹, H. C. Shi³, X. P. Li¹

¹National Institute of Metrology, mengt@nim.ac.cn, Beijing, P. R. China

²Guangzhou Institute of Energy Testing, Guangzhou, P. R. China

³Beijing University of Chemical Technology, Beijing, P. R. China

Presenter: Dr. Liang Zhang (Tao Meng)

Lisbon, 06.2019

E-mail: mengt@nim.ac.cn





- **1** Introduction
- **Measurement of flow stability**
- **13** Experiment on buffer tank method
- Experiment on high constant water head tank method
- **Conclusions**





- **1** Introduction
- **Measurement of flow stability**
- **Experiment on buffer tank method**
- Experiment on high constant water head tank method
- **Conclusions**



1. Introduction

01

Flow stability is an important **technical index** of flow standard facilities.

It is of great significance to find out the causes of the fluctuation for improving the calibration capability and decreasing the uncertainty.

02

The buffer tank and the high constant water head tank are two kinds of methods for stabilizing flow widely used in the water flow facilities, the actual effect of them was studied by the experiments in this paper.






- **1** Introduction
- **Measurement of flow stability**
- **13** Experiment on buffer tank method
- Experiment on high constant water head tank method
- **Conclusions**




2. Measurement of flow stability

2.1 The flow stability test devices



a pressure sensor + a flow meter in series





2. Measurement of flow stability

2.2 The flow stability test system

Tao Meng, Shangchun Fan, Chi Wang, Huichao Shi, Xiaopeng Li. A flow stability evaluation method based on flow-pressure correlation. Flow Measurement & Instrumentation, 2018(64): 155 - 163.

(1) The amplitude of flow fluctuation

$$D_{q} = \sqrt{\frac{\sum_{i=1}^{N} (q_{i} - \overline{q})^{2}}{N-1}} / \overline{q}$$
 by flowmeter in a single flow measurement

Standard Deviation

(2) The frequency of flow fluctuation

by performing **FFT** analysis on the pressure signal

(3) The direction of fluctuations source

obvious positive correlation (0.3<
$$r_{\rm qp}$$
<1)
$$r_{\rm qp} = \frac{\sum_{\rm n=1}^{\rm N} q({\rm n})p({\rm n+m})}{\sigma_{\rm q}\sigma_{\rm p}}$$
obvious positive correlation (0.3< $r_{\rm qp}$ <1)
from the up

Correlation Analysis

obvious positive correlation $(0.3 < r_{qp} < 1)$

from the upstream

from the **downstream**





- **Introduction**
- **Measurement of flow stability**
- **Experiment on buffer tank method**
- Experiment on high constant water head tank method
- **Conclusions**



3.1 Experimental facility and scheme

➤ Pipe diameter: DN80


> Flow range: (15~120) m³/h

> outlet pressure : (0.1~0.2) MPa.

> From 15m³/h, increased by about

10m³/h each time

Test on 1# facility




regulating valves



3.2 Test results of 1# facility

Flow Rate (m³/h)	Flow Fluctuation Amplitude (%)	Flow Fluctuation Frequency (Hz)	Correlation Coefficient
15	1.36	1.45	0.70
20	0.95	1.48	0.77
30	0.34	1.61	0.77
40	0.18	1.73	0.68
50	0.13	1.91	0.61
61	0.10		0.49
71	0.09		0.56
80	0.09		0.39
90	0.09		0.38
100	0.08		0.33
109	0.09		0.23
120	0.08		0.25






3.2 Test results of 1# facility

Flow Rate (m³/h)	Flow Fluctuation Amplitude (%)	Flow Fluctuation Frequency (Hz)	Correlation Coefficient
15	1.36	1.45	0.70
20	0.95	1.48	0.77
30	0.34	1.61	0.77
40	0.18	1.73	0.68
50	0.13	1.91	0.61
61	0.10		0.49
71	0.09		0.56
80	0.09		0.39
90	0.09		0.38
100	0.08		0.33
109	0.09		0.23
120	80.0		0.25

Flow Fluctuation Amplitude




The flow fluctuation amplitude showed a trend of rapid decrease with the increase of flowrate



3.2 Test results of 1# facility

Flow Rate (m³/h)	Flow Fluctuation Amplitude (%)	Flow Fluctuation Frequency (Hz)	Correlation Coefficient
15	1.36	1.45	0.70
20	0.95	1.48	0.77
30	0.34	1.61	0.77
40	0.18	1.73	0.68
50	0.13	1.91	0.61
61	0.10		0.49
71	0.09		0.56
80	0.09		0.39
90	0.09		0.38
100	0.08		0.33
109	0.09		0.23
120	0.08		0.25

In terms of the characteristics of fluctuation frequency, the main fluctuation frequency was about 1.5Hz in the low-flow rate area. However, when the flow rate is greater than 60m³/h, there was no obvious characteristic frequency.




FFT spectrum analysis



3.2 Test results of 1# facility

Correl	ation	analy	sis of
pressur	e and	flow	signals


Flow Rate (m³/h)	Flow Fluctuation Amplitude (%)	Flow Fluctuation Frequency (Hz)	Correlation Coefficient
15	1.36	1.45	0.70
20	0.95	1.48	0.77
30	0.34	1.61	0.77
40	0.18	1.73	0.68
50	0.13	1.91	0.61
61	0.10		0.49
71	0.09		0.56
80	0.09		0.39
90	0.09		0.38
100	0.08		0.33
109	0.09		0.23
120	0.08		0.25



It was an obvious **positive** correlation (0.6< r_{pq} <0.8) between flow and pressure, and it can be inferred that the fluctuation source mainly was at the **upstream** of the measurement system.




3.2 Test results of 1# facility







3.2 Test results of 1# facility








- **Introduction**
- **Measurement of flow stability**
- **13** Experiment on buffer tank method
- Experiment on high constant water head tank method
- **Conclusions**

4. Experiment on high constant water head tank method

4.1 Experimental facility and scheme



storage tank

➤ Pipe diameter: DN100

➤ Flow range: (30~120) m³/h

> outlet pressure : (0.1~0.3) MPa.

Two different methods for flow stabilization:

- (1) High constant water head tank.
- (2) Buffer tank

The regulating valve VT1 of this pipeline was a linear ball valve, and its flow adjustment range was (30~200) m³/h.




4.2 Test results of 2# facility

Experiment al Group	Experiment Number	Stabilizing Pressure Method and Working Condition	Flow Rate (m³/h)	Fluctuation Amplitude (%)	Pipeline Pressure (kPa)	Valve Opening (%)
	H-01	constant head	30	0.52	175	28
Group 1	H-02		50	0.36	171	40
	H-03	tank	120	0.22	143	70
	H-04	buffer topk	30	0.50	175	29
Group 2	H-05	buffer tank,	50	0.38	172	40
	H-06	mid-pressure	120	0.22	164	66
Group 3	H-07	buffer tank,	50	0.47	299	31
Group 3	H-08 high-press	high-pressure	120	0.31	289	54
Group 4	H-09	buffer tank,	50	0.20	39	100
Group 4	H-10	low-pressure	120	0.18	99	100



4.2 Test results of 2# facility

Experimental Group	Experiment Number	Stabilizing Pressure Method and Working Condition	Flow Rate (m³/h)	Fluctuation Amplitude (%)	Pipeline Pressure (kPa)	Valve Opening (%)
	H-01		30	0.52	175	28
Group 1	H-02	constant head tank	50	0.36	171	40
	H-03		120	0.22	143	70
	H-04	had a carlo askal	30	0.50	175	29
Group 2	H-05	buffer tank, mid-	50	0.38	172	40
	H-06	pressure	120	0.22	164	66
Crown 2	H-07	buffer tank, high-	50	0.47	299	31
Group 3	H-08	pressure	120	0.31	289	54
Crown 4	H-09	buffer tank, low-	50	0.20	39	100
Group 4	H-10	pressure	120	0.18	99	100




Compared with the result of Group 1 and Group 2, it can be found that the fluctuation amplitude of the two stabilizing flow methods were very close at different flow rate.




4.2 Test results of 2# facility

Experimental Group	Experiment Number	Stabilizing Pressure Method and Working Condition	Flow Rate (m³/h)	Fluctuation Amplitude (%)	Pipeline Pressure (kPa)	Valve Opening (%)
	H-01		30	0.52	175	28
Group 1	H-02	constant head tank	50	0.36	171	40
	H-03		120	0.22	143	70
	H-04	h	30	0.50	175	29
Group 2	H-05	buffer tank, mid-	50	0.38	172	40
	H-06	pressure	120	0.22	164	66
Croup 2	H-07	buffer tank, high-	50	0.47	299	31
Group 3	H-08	pressure	120	0.31	289	54
Croup 4	H-09	buffer tank, low-	50	0.20	39	100
Group 4	H-10	pressure	120	0.18	99	100



experiment H-01 (water tower)




experiment H-04 (buffer tank)

Only some weak signals were found around 1Hz



4.2 Test results of 2# facility

Experimental Group	Experiment Number	Stabilizing Pressure Method and Working Condition	Flow Rate (m³/h)	Fluctuation Amplitude (%)	Pipeline Pressure (kPa)	Valve Opening (%)
	H-01		30	0.52	175	28
Group 1	H-02	constant head tank	50	0.36	171	40
	H-03		120	0.22	143	70
	H-04	buffer took mid	30	0.50	175	29
Group 2	H-05	buffer tank, mid-	50	0.38	172	40
	H-06	pressure	120	0.22	164	66
Croup 2	H-07	buffer tank, high-	50	0.47	299	31
Group 3	H-08	pressure	120	0.31	289	54
Crown 4	H-09	buffer tank, low-	50	0.20	39	100
Group 4	H-10	pressure	120	0.18	99	100



Correlation analysis of pressure and flow signals

Fluctuation Source negative correlation




downstream of the measuring point



4.2 Test results of 2# facility

Experimental Group	Experiment Number	Stabilizing Pressure Meth and Working Condition
	H-01	
Group 1	H-02	constant head to
	H-03	
	H-04	huffer took mi
Group 2	H-05	buffer tank, mic
	H-06	pressure
0	H-07	buffer tank, hig
Group 3	H-08	pressure
0,000,000,4	H-09	buffer tank, lov
Group 4	H-10	pressure



0.75-0.75-0.25-0.25-0.75-0.25-0.75-0.

Correlation analysis of pressure and flow signals

Fluctuation Source

negative correlation


downstream of the measuring point


regulating valve VT1



4.2 Test results of 2# facility

Experimental Group	Experiment Number	Stabilizing Pressure Method and Working Condition	Flow Rate (m³/h)	Fluctuation Amplitude (%)	Pipeline Pressure (kPa)	Valve Opening (%)
	H-01		30	0.52	175	28
Group 1	H-02	constant head tank	50	0.36	171	40
	H-03		120	0.22	143	70
	H-04	buffor to plane	30	0.50	175	29
Group 2	H-05	buffer tank, mid-	50	0.38	172	40
	H-06	pressure	120	0.22	164	66
Crown 2	H-07	buffer tank, high-	50	0.47	299	31
Group 3	H-08	pressure	120	0.31	289	54
Crown 4	H-09	buffer tank, low-	50	0.20	39	100
Group 4	H-10	pressure	120	0.18	99	100









- **1** Introduction
- **Measurement of flow stability**
- **13** Experiment on buffer tank method
- Experiment on high constant water head tank method
- **Conclusions**



5. Conclusions

01

The amplitude and frequency of flow fluctuation are not only the technical indicators to represent the flow stability of the facility, through the analysis of the direction of the fluctuation source and the change rule of flow stability at different working conditions, the causes of the fluctuation can be effectively found.

02

For flow facilities with the **buffer tank**, working in **low-efficiency** areas of pumps should be avoided; and for facilities with the **high** constant water head tank, the reasonable regulating valve groups should be designed to avoid excessive local pressure loss, so as to obtain good flow stability.



I how Muehl



